



STACKING WASHER DIN ISO 10069-2 THRUST WASHER

2441.3.



Mounting example



2441.3. Stacking washer DIN ISO 10069-2

Spring-ø	16	20	25	32	40	50	63	80	100	125
d ₁	20	25	30	40	50	60	80	100	120	150
d ₅	6.5	8.5	10.5	13.5	13.5	16.5	16.5	20.5	20.5	26
s	4	4	5	5	5	6	6	8	8	8


Material:

Brass


Ordering Code (example):

Stacking washer DIN ISO 10069-2	=	2441.3.
Spring diameter Spring-ø	50 mm =	050
Order No	=	2441.3. 050

244.4.



Mounting example



244.4. Thrust washer

Spring-ø	16	20	25	32	40	50	63	80	100	125
d ₁	20	26	32	40	50	60	80	100	120	150
d ₅	6.5	8.5	10.5	13.5	13.5	16.5	16.5	20.5	20.5	26
s	1	1.5	2	2.5	2.5	3	3	4	4	5

Material:

St 37

Ordering Code (example):

Thrust washer	=	244.4.
Spring diameter Spring-ø	50 mm =	050
Order No	=	244.4. 050